


Female Quick Connects

Quick Connect Has Two Parts - Receptacle (Female) & Mating Tab (Male)

VINYL INSULATED



NYLON FULLY INSULATED



NON-INSULATED



NYLON INSULATED WITH METAL SLEEVE




W	Red 22-16 AWG				Blue 16-14 AWG				Yellow 12-10 AWG			
	Part #	Qty	Part #	Qty	Part #	Qty	Part #	Qty	Part #	Qty	Part #	Qty
.110	1749A	1000	—	—	1849A	1000	—	—	—	—	—	—
.110	1749C	100	1749PT	100	1849C	100	1849PT	100	—	—	—	—
.110	1749D	10	1749KT	18	1849D	10	1849KT	12	—	—	—	—
.110	1749M	3	1749QT	3	1849M	3	1849QT	3	—	—	—	—
.187	1751A	1000	—	—	1851A	1000	—	—	—	—	—	—
.187	1751C	100	1751PT	100	1851C	100	1851PT	100	—	—	—	—
.187	1751D	10	1751KT	18	1851D	10	1851KT	12	—	—	—	—
.187	—	—	1751QT	3	—	—	1851QT	3	—	—	—	—
.205	—	—	—	—	1853A	1000	—	—	—	—	—	—
.205	—	—	—	—	1853C	100	1853PT	100	—	—	—	—
.205	—	—	—	—	1853D	8	—	—	—	—	—	—
.205	—	—	—	—	1853M	3	1853QT	3	—	—	—	—
.250	1755A	1000	—	—	1855A	1000	—	—	1955A	500	—	—
.250	1755C	100	1755PT	100	1855C	100	1855PT	100	1955G	100	—	—
.250	1755H	19	1755KT	18	1855H	20	1855KT	20	1955C	50	1955PT	50
.250	1755D	10	1755QT	3	1855D	12	—	—	1955H	15	1955KT	15
.250	1755M	3	—	—	1855M	5	1855QT	5	1955D	9	—	—
.250	—	—	—	—	—	—	—	—	1955M	3	1955QT	3
.250	1765A	500	—	—	1865A	500	—	—	1965A	500	—	—
.250	1765G	100	—	—	1865G	100	—	—	1965G	100	—	—
.250	1765C	50	1765PT	50	1865C	50	1865PT	50	1965C	25	1965PT	25
.250	1765H	10	1765KT	10	1865H	10	1865KT	10	—	—	1965KT	3
.250	1765D	6	—	—	1865D	6	—	—	1965D	2	—	—
.250	1765M	2	1765QT	2	1865M	2	1865QT	2	1965M	1	1965QT	1
.187	—	—	—	—	2451A	1000	2451C	100	—	—	—	—
.205	—	—	—	—	2453A	1000	2453C	100	—	—	—	—
.250	2355A	1000	2355C	100	2455A	1000	2455C	100	2555A	500	2555C	50
.250	2955A	500	2955C	25	3055A	500	3055C	25	3155A	250	3155C	20

Male Quick Connects

Mating Male Tab To Above Listed Female Receptacles

VINYL INSULATED



NYLON FULLY INSULATED



NON-INSULATED



NYLON INSULATED WITH METAL SLEEVE



W	Red 22-16 AWG				Blue 16-14 AWG				Yellow 12-10 AWG			
	Part #	Qty	Part #	Qty	Part #	Qty	Part #	Qty	Part #	Qty	Part #	Qty
.110	1750A	1000	—	—	1850A	1000	—	—	—	—	—	—
.110	1750C	100	1750PT	100	1850C	100	1850PT	100	—	—	—	—
.110	1750D	10	1750KT	18	1850D	10	1850KT	12	—	—	—	—
.110	1750M	3	1750QT	3	1850M	3	1850QT	3	—	—	—	—
.187	1752A	1000	—	—	1852A	1000	—	—	—	—	—	—
.187	1752C	100	1752PT	100	1852C	100	1852PT	100	—	—	—	—
.187	1752D	10	1752KT	18	1852D	10	1852KT	12	—	—	—	—
.187	—	—	1752QT	3	—	—	1852QT	3	—	—	—	—
.250	1756A	1000	—	—	1856A	1000	—	—	1956A	500	—	—
.250	1756C	100	1756PT	100	1856C	100	1856PT	100	1956G	100	—	—
.250	1756D	10	1756KT	18	1856H	19	1856KT	19	1956C	50	1956PT	50
.250	1756M	3	1756QT	3	1856D	12	—	—	1956H	15	1956KT	15
.250	—	—	—	—	1856M	5	1856QT	5	1956D	9	—	—
.250	—	—	—	—	—	—	—	—	1956M	3	1956QT	3
.250	1764A	500	—	—	1864A	500	—	—	1964A	500	—	—
.250	1764G	100	—	—	1864G	100	—	—	1964G	100	—	—
.250	1764C	50	1764PT	50	1864C	25	1864PT	25	1964C	25	1964PT	25
.250	1764H	10	1764KT	10	1864H	10	1864KT	10	—	—	1964KT	3
.250	1764D	6	—	—	1864D	6	—	—	1964D	2	—	—
.250	1764M	2	1764QT	2	1864M	2	1864QT	2	1964M	1	1964QT	1
.187	—	—	—	—	2452A	1000	2452C	100	—	—	—	—
.250	2356A	1000	2356C	100	2456A	1000	2456C	100	2556A	500	2556C	50
.250	2956A	500	2956C	25	3056A	500	3056C	25	3156A	250	3156C	20